




[illegible]

FIG. 1

[illegible]

**FIG. 2**

PRIOR ART







FIG. 6




FIG. 7




FIG. 8

This diagram shows an exploded perspective view of a key assembly. The components are labeled with numbers: 20 (the main body of the key), 50 (the top surface of the key head), 54 (the cross-shaped cutout in the head), 52 (two circular holes in the head), 42 (a cross-shaped insert), 22 (a circular base for the insert), 58 (the insert itself), 26 (a bracket with four pins), 28 (four pins), 40 (two pins), 48 (a small component), 46 (a rectangular component), 32 (a rectangular plate), 36 (four pins), 34 (a rectangular plate), 30 (a rectangular plate), 56 (the bottom surface of the key head), and 24 (a rectangular plate). Arrows indicate the assembly sequence and alignment of the parts.

FIG. 9




FIG. 10




FIG. 11